

PLEASE THINK BEFORE YOU PRINT

Release notes

SMART Product Drivers 10 for Windows® and Mac computers

About these release notes

These release notes document changes in SMART Product Drivers 10 (formerly SMART Board™ drivers 10) and its service packs for Windows® operating systems and Mac OS X operating system software.

Product information

SMART Product Drivers is software that allows your computer to detect input from your SMART Board interactive whiteboard or other SMART products. These drivers are included with SMART Notebook™ collaborative learning software for schools and SMART Meeting Pro™ Premium and SMART Meeting Pro software for businesses.

Extraordinary made simple™

SMART™

SMART Product Drivers 10.7 updates

About this release

This software update for Windows operating systems and Mac operating system software includes support for SMART Board X800 series interactive whiteboards. It also features improved support for Windows Ink Aware applications and enables administrators to prevent the installation of unsigned drivers.

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART Product Drivers	10.7.82.0	October 21, 2010
SMART Product Drivers installation	10.7.81.0	
Instant conferencing	10.7.81.0	
SMART Board Diagnostics	10.7.81.0	

Mac OS X operating system software

Component	Version	Date (if applicable)
SMART Product Drivers	10.7.87.0	November 9, 2010
SMART Product Drivers installation	10.7.88.0	
Instant conferencing	10.7.87.0	
SMART Board Diagnostics	10.7.87.0	

Computer requirements

No changes from previous release.

New features

General

- Support for SMART Board X800 series interactive whiteboards
- Support for SMART Board 8070i interactive displays
- Support for the Cat 5 to USB extender (SBX800 CAT5-XT) that enables you to extend the USB connection between your computer and a SMART Board X800 series interactive whiteboard an additional 50' (15 m)

Windows operating systems

- Ink Aware software now includes support for the following:
 - Microsoft® Office 2010 (Excel®, Word, PowerPoint® and OneNote®)
 - Native tools in Microsoft Office 2010
 - OpenOffice.org™ 3.2.0 (Calc, Writer and Impress) in English, German and Danish
 - Hyperlinks
- Enables administrators to prevent the installation of third-party unsigned drivers

Mac operating system software

- Support for Microsoft Office for Mac 2008

Known issues

General

- Your digital ink notes appear shifted from where you write them when your display is set to an aspect ratio other than 4:3.
- Non-injected digital ink notes disappear when you switch from one Excel spreadsheet to another.
- Text boxes and tables can interfere with digital ink injections.

Windows operating systems

- Ink Aware software isn't compatible with the 64-bit version of Microsoft Office 2010.

Related release notes

- *SMART Notebook software 10 for Windows and Mac computers* (smarttech.com/kb/126571)
- *SMART Meeting Pro Premium* (smarttech.com/kb/144278)
- *SMART Meeting Pro* (smarttech.com/kb/141332)

SMART Product Drivers 10.6 SP2 updates

About this release

This software update for Windows operating systems and Mac operating system software includes support for the SMART Board 6052i interactive display and SMART Document Camera™ 330 (Windows computers only). It also features improved support for Ink Aware applications and Touch Recognition features.

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART Product Drivers	10.6.175.2	June 15, 2010
Driver installation	10.6.175.2	
Instant conferencing	10.6.175.2	
SMART Board Diagnostics	10.6.175.2	June 15, 2010
Language setup	2.2.16.2	
SMART Product Update	4.0.89.4	

Mac OS X operating system software

Component	Version	Date (if applicable)
SMART Product Drivers	10.6.134.2	July 2, 2010
SMART Product Drivers installation	10.6.134.2	
SMART Product Update	4.0.115.1	

Computer requirements

No changes from previous release.

Highlights

- Onscreen keyboard has enhanced security for password fields.
- Ink Aware software improvements:
 - Faster digital ink notes over PowerPoint animations.
 - Better-positioned **Restore Ink** bubble.
 - Addition of **Restore Ink** icon to Microsoft Office application toolbars.

5 | **RELEASE NOTES** – SMART PRODUCT DRIVERS 10 FOR WINDOWS AND MAC COMPUTERS

- New dialog box at the end of PowerPoint slide shows prompts you to save your digital ink notes.
- Better save-on-close functionality: there's now only one prompt, and the Office application menu items **Save** and **Exit** are no longer grayed out.
- Improved support for digital ink features in .xlsx (Excel 2007) files imported into Excel 2003.
- Touch Recognition improvements:
 - Ink Aware and interaction with Excel works as expected.
 - You can now select side bar tools on the desktop ink layer with your finger.
- The diagnostic web server application is no longer included with the installation.

Known issues

- Your digital ink notes appear shifted from where you write them when your display is set to a resolution other than 4:3.
- Non-injected digital ink notes disappear when you switch from one Excel spreadsheet to another.
- Text boxes and tables can interfere with digital ink injections.
- Linked PowerPoint slide shows don't perform as expected when Ink Aware is enabled.

Related release notes

- *SMART Notebook Software 10 for Windows and Mac Computers* (smarttech.com/kb/126571)
- *SMART Meeting Pro* (smarttech.com/kb/141332)
- *SMART Meeting Pro Premium* (smarttech.com/kb/144278)

SMART Product Drivers 10.6 SP1 updates

About this release

This software update for Windows operating systems and Mac operating system software includes support for the SC12 serial controller module and resolves certain issues.

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART Product Drivers	10.6.106.1	March 3, 2010
Driver installation	10.6.106.1	
Instant conferencing	10.6.106.1	
SMART Board Diagnostics	10.6.106.1	March 3, 2010
Language setup	2.2.14.1	
SMART Product Update	4.0.85.1	

Mac OS X operating system software

Component	Version	Date (if applicable)
SMART Product Drivers	10.6.64.1	March 20, 2010
SMART Product Drivers installation	10.6.64.1	
SMART Product Update	4.0.115.1	

Computer requirements

Windows operating systems

In addition to the previous requirements, you must install the Microsoft Visual C++ 2008 SP1 redistributable before installing SMART Product Drivers. This software is included with this SMART Product Drivers download.

Mac OS X operating system software

No changes from previous release.

Resolved issues

General

- Support for the SC12 serial controller module

Windows operating systems

- Resolution of the issue of touch at the login screen for Windows XP operating systems

Mac OS X operating system software

- Resolution of the sleep issue for SC9
- Resolution of Ink Aware issues with PowerPoint
- Resolution of Adobe® Illustrator® issues with SMART Product Drivers
- Resolution of other issues

Related release notes

- *SMART Notebook Software 10 for Windows and Mac Computers* ([document 126571](#))
- *SMART Meeting Pro* ([document 141332](#))
- *SMART Meeting Pro Premium* ([document 144278](#))

SMART Product Drivers 10.6 updates

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART control panel	10.1.17.0	December 8, 2009
Software	10.6.48.0	December 15, 2009
Driver installation	10.6.48.0	
Instant conferencing	10.6.48.0	
SMART Board Diagnostics	10.6.48.0	December 15, 2009
Language setup	2.2.7.0	
SMART Product Update	4.0.85.1	

Mac OS X operating system software

Component	Version	Date (if applicable)
Software	10.6.48.0	December 24, 2009
Welcome Center	10.6.22.0	December 31, 2009

Computer requirements

Windows operating systems

- Pentium® III 750 MHz processor or faster recommended
- 512 MB of RAM (1 GB recommended)
- 800 MB of free hard disk space for minimum installation (2 GB for full installation with Gallery collections)
- Windows XP, Windows Vista® or Windows 7 operating system
- Internet Explorer® Internet browser 6.0 or later
- Adobe Flash® Player 10
- Windows Media® Player 9 or later for SMART Recorder
- DirectX® technology 8.1 or later for SMART Video Player

Mac OS X operating system software

- 1 GHz PowerPC® G4 or G5 processor or Intel® processor
- 1 GB of RAM
- 800 MB of free hard disk space for minimum installation (2 GB for full installation with Gallery collections)
- Mac OS X operating system software 10.5.8 or 10.6.x
- Safari application program 1.3.2 or later
- Adobe Flash Player 10

Highlights

Windows operating systems

- Windows 7 support
- Reduction in download size (customization of the Handwriting Recognition installation enables the installer to exclude unwanted handwriting recognition languages from the download)

Mac OS X operating system software

- Mac OS X 10.6 (Snow Leopard) support

Resolved issues

General

- Resolution of various translation issues

Windows operating systems

- Resolution of various Ink Aware issues

Mac OS X operating system software

- Resolution of issue regarding the unwanted joining of lines
- Ability to use Ink Aware without a connected SMART Board interactive whiteboard

SMART Product Drivers 10 SP7 updates

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART Board control panel	10.0.528.7	September 17, 2009
SMART Board Diagnostics	10.0.528.7	September 17, 2009
SMART Keyboard	10.0.232.4	January 25, 2009
Floating Tools	10.0.232.4	January 25, 2009
Ink layer	10.0.232.4	January 25, 2009
Ink Aware	10.0.232.4	January 25, 2009
Orientation	10.0.232.4	January 25, 2009
Display Controller	10.0.232.4	January 25, 2009
Bridgit™ software	3.4.104.1	September 16, 2008
Language setup	1.2.51.2	September 23, 2008
SMART Product Update	4.0.85.1	

Mac OS X operating system software

Component	Version	Date (if applicable)
SMART Board control panel	10.0.432.7	September 17, 2009
SMART Board Diagnostics	10.0.284.4	January 8, 2009
SMART Keyboard	10.0.284.4	January 8, 2009
Floating Tools	10.0.284.4	January 8, 2009
Ink layer	10.0.284.4	January 8, 2009
Ink Aware	10.0.284.4	January 8, 2009
Orientation	10.0.284.4	January 8, 2009
Display Controller	10.0.284.4	January 8, 2009
Bridgit software	3.4.104.1	September 16, 2008
SMART Product Update	1.1.20.0	

Computer requirements

Windows operating systems

- Pentium II 450 MHz processor
- 256 MB of RAM (512 MB recommended)
- 180 MB free hard disk space for minimum installation (840 MB for full installation with Gallery collections)
- Windows 2000, Windows XP or Windows Vista operating system
- Internet Explorer Internet browser 6.0 or later
- Adobe Flash Player 8 or later

Mac OS X operating system software

- 700 MHz processor (1 GHz or faster recommended) PowerPC G3, G4 or G5 processor or Intel processor (universal binary)
- 256 MB of RAM (512 MB recommended)
- 85 MB of free hard disk space for minimum installation (825 MB for full installation with Gallery collections)
- Mac OS X operating system software 10.5.8 or 10.5.9
- Safari application program 1.3.2 or later

Highlights

General

- Support for the dual-touch, dual-write SMART Board D600 series interactive whiteboard

Mac OS X operating system software

- Support for Mac OS X operating system software 10.5.9

Resolved issues

Windows operating systems

- Ability to use Windows Group Policy (GPO) to push MSI commands

SMART Product Drivers 10 SP4 updates

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART Board control panel	10.0.232.4	January 25, 2009
SMART Board Diagnostics	10.0.232.4	January 25, 2009
SMART Keyboard	10.0.232.4	January 25, 2009
Floating Tools	10.0.232.4	January 25, 2009
Ink layer	10.0.232.4	January 25, 2009
Ink Aware	10.0.232.4	January 25, 2009
Orientation	10.0.232.4	January 25, 2009
Display Controller	10.0.232.4	January 25, 2009
Bridgit software	3.4.101.1	September 4, 2008
Language setup	1.2.37.1	September 23, 2008
SMART Product Update	3.1.64.2	

Mac OS X operating system software

Component	Version	Date (if applicable)
SMART Board control panel	10.0.284.4	January 8, 2009
SMART Board Diagnostics	10.0.284.4	January 8, 2009
SMART Keyboard	10.0.284.4	January 8, 2009
Floating Tools	10.0.284.4	January 8, 2009
Ink layer	10.0.284.4	January 8, 2009
Ink Aware	10.0.284.4	January 8, 2009
Orientation	10.0.284.4	January 8, 2009
Display Controller	10.0.284.4	January 8, 2009
Bridgit software	3.4.104.1	September 16, 2008
SMART Product Update	1.1.20.0	

Computer requirements

No changes from previous release.

Resolved issues

Windows operating systems

- If your computer with SMART Board drivers is connected to multiple SMART products, you can write digital ink in an Ink Aware application on one screen and then select objects and complete other mouse tasks in another Ink Aware application on another display.
- Ink Aware now works with SMART Board interactive display frames.
- If you're using a SMART Board interactive display frame, and you close the ink layer and then attempt to draw digital ink on the desktop with the pencil, the ink layer reappears.
- On SMART Board interactive display frames, the SMART Board control panel always displays the correct firmware version.
- If your computer with SMART Board drivers is connected to multiple SMART products when you open dialog boxes in the SMART Board control panel, the dialog boxes appear in the same display as the control panel.
- The issue that was causing the Floating Tools toolbar to partially disappear has been corrected.
- Double-clicking the ink layer now takes a single screen capture (if **Always Save Ink** is selected).
- When you press the ink layer, a shortcut menu appears. When you press the layer again, the shortcut menu closes.
- SMART Board drivers now includes better support for multiple Floating Tools toolbars.
- When you connect a SMART Board interactive whiteboard with Touch Recognition to your Windows computer, a bubble appears beside the SMART Board Tools icon. This bubble allows you to disable Touch Recognition.

Mac OS X operating system software

- When you connect a SMART Board interactive whiteboard with Touch Recognition to your Mac computer, a bubble appears beside the SMART Board Tools icon. This bubble allows you to disable Touch Recognition.

SMART Product Drivers 10 SP3 updates

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART Board control panel	10.0.188.3	November 20, 2008
SMART Board Diagnostics	10.0.188.3	November 20, 2008
SMART Keyboard	10.0.188.3	November 20, 2008
Floating Tools	10.0.188.3	November 20, 2008
Ink layer	10.0.188.3	November 20, 2008
Ink Aware	10.0.188.3	November 20, 2008
Orientation	10.0.188.3	November 20, 2008
Display Controller	10.0.188.3	November 20, 2008
Bridgit software	3.4.101.1	September 4, 2008
Language setup	1.2.37.1	September 23, 2008
SMART Product Update	3.1.63.1	November 7, 2008

Mac OS X operating system software

Component	Version	Date (if applicable)
SMART Board control panel	10.0.266.3	November 20, 2008
SMART Board Diagnostics	10.0.266.3	November 20, 2008
SMART Keyboard	10.0.266.3	November 20, 2008
Floating Tools	10.0.266.3	November 20, 2008
Ink layer	10.0.266.3	November 20, 2008
Ink Aware	10.0.266.3	November 20, 2008
Orientation	10.0.266.3	November 20, 2008
Display Controller	10.0.266.3	November 20, 2008
Bridgit software	3.4.104.1	September 16, 2008
SMART Product Update	1.1.20.0	

Computer requirements

No changes from previous release.

Highlights

General

- Automatic input detection support for SMART Board 600 series interactive whiteboards



NOTE

This feature is disabled by default. If your SMART Board 600 series interactive whiteboard supports this feature, you can enable it in the mouse settings of the SMART Board control panel.

Resolved issues

General

- A known issue with ambient lighting and the SMART Board V200 series interactive whiteboard has been resolved:
 - “For best results ensure the projected image fills the area of the board” appears when you orient a SMART Board V200 series interactive whiteboard.
 - If you select the **Projected image fills the area of the board** check box in the SMART Board control panel for your V200 series interactive whiteboard, SMART Board drivers optimizes the orientation appropriately.

Mac OS X operating system software

- If you minimize Floating Tools in Mac OS X operating system software and then log off, Floating Tools remain minimized when you log on again.

SMART Product Drivers 10 SP2 updates

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART Board control panel	10.0.186.2	October 22, 2008
SMART Board Diagnostics	10.0.186.2	October 22, 2008
SMART Keyboard	10.0.186.2	October 22, 2008
Floating Tools	10.0.186.2	October 22, 2008
Ink layer	10.0.186.2	October 22, 2008
Ink Aware	10.0.186.2	October 22, 2008
Orientation	10.0.186.2	October 22, 2008
Display Controller	10.0.186.2	October 22, 2008
Bridgit software	3.4.101.1	September 5, 2008
Language setup	1.2.37.1	September 23, 2008
SMART Product Update	3.1.58.1	September 23, 2008

Mac OS X operating system software

Component	Version	Date (if applicable)
SMART Board control panel	10.0.224.2	November 5, 2008
SMART Board Diagnostics	10.0.224.2	November 5, 2008
SMART Keyboard	10.0.224.2	November 5, 2008
Floating Tools	10.0.224.2	November 5, 2008
Ink layer	10.0.224.2	November 5, 2008
Ink Aware	10.0.224.2	November 5, 2008
Orientation	10.0.224.2	November 5, 2008
Display Controller	10.0.224.2	November 5, 2008
Bridgit software	3.4.104.1	September 16, 2008
SMART Product Update	1.1.20.0	

Computer requirements

No changes from previous release.

Highlights

Windows operating systems

- Adobe Acrobat® 9 support

Mac OS X operating system software

- Improvements to support for SMART Board interactive display frames
- New installation option that allows you to enable or disable the automatic start of SMART Board Tools during logon

Resolved issues

Windows operating systems

- When you draw vertical lines quickly on a SMART Board V200 series interactive whiteboard, the lines no longer bend to the left or right.
- The default double-click zone is the smallest possible area for SMART Board V200 series interactive whiteboards.
- If you draw digital ink with one pen and then pick up another pen from the pen tray while continuing to touch the surface, the digital ink changes to the newly selected pen's color.
- Check boxes that had previously been removed from the *SMART Board Interactive Display View* window in SMART Board Diagnostics have been restored.
- There have been several minor changes to the wording in the user interface for the SMART Board interactive display frame.
- When orienting the SMART Board interactive display frame, you can go back to the previous orientation point by pressing the screen with the pencil's eraser.
- You can now use the four colored pencils with the SMART Board interactive display frame.
- The last point in the orientation screen now behaves like all the other orientation points.
- Ink Aware supports the Danish version of OpenOffice.org.

Mac OS X operating system software

- Fixes to Ink Aware support
- Fixes to Floating Tools behavior

SMART Product Drivers 10 SP1 updates

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART Board control panel	10.0.163.1	July 31, 2008
SMART Board Diagnostics	10.0.163.1	July 31, 2008
SMART Keyboard	10.0.163.1	July 31, 2008
Floating Tools	10.0.123.0	April 3, 2008
Ink layer	10.0.163.1	July 31, 2008
Ink Aware	10.0.163.1	July 31, 2008
Orientation	10.0.163.1	July 31, 2008
Display Controller	10.0.163.1	July 31, 2008
Bridgit software	3.3.23.0	January 10, 2008
Language setup	1.2.36.1	July 28, 2008
SMART Product Update	3.1.55.1	July 25, 2008

Mac OS X operating system software

Component	Version	Date (if applicable)
SMART Board control panel	10.0.147.1	July 30, 2008
SMART Board Diagnostics	10.0.147.1	July 30, 2008
SMART Keyboard	10.0.147.1	July 30, 2008
Floating Tools	10.0.147.1	July 30, 2008
Ink layer	10.0.147.1	July 30, 2008
Ink Aware	10.0.147.1	July 30, 2008
Orientation	10.0.147.1	July 30, 2008
Display Controller	10.0.147.1	July 30, 2008
Bridgit software	3.3.23.0	January 10, 2008
SMART Product Update	1.1.19.0	

Computer requirements

No changes from previous release.

Highlights

Windows operating systems

- Windows XP SP3 support

Resolved issues

Windows operating systems

- Fixes to Ink Aware support for Office 2007

SMART Board Drivers 10 summary

Software component version numbers

Windows operating systems

Component	Version	Date (if applicable)
SMART Board control panel	10.0.123.0	April 3, 2008
SMART Board Diagnostics	10.0.123.0	April 3, 2008
SMART Keyboard	10.0.123.0	April 3, 2008
Floating Tools	10.0.123.0	April 3, 2008
Ink layer	10.0.123.0	April 3, 2008
Ink Aware	10.0.123.0	April 3, 2008
Orientation	10.0.123.0	April 3, 2008
Display Controller	10.0.123.0	April 3, 2008
Bridgit software	3.3.23.0	January 10, 2008
Language setup	1.2.32.0	April 3, 2008
SMART Product Update	3.1.44.0	April 25, 2008

Mac OS X operating system software

Component	Version	Date (if applicable)
SMART Board control panel	10.0.52.0	April 2, 2008
SMART Board Diagnostics	10.0.52.0	April 2, 2008
SMART Keyboard	10.0.52.0	April 2, 2008
Floating Tools	10.0.52.0	April 2, 2008
Ink layer	10.0.52.0	April 2, 2008
Ink Aware	10.0.52.0	April 2, 2008
Orientation	10.0.52.0	April 2, 2008
Display Controller	10.0.52.0	April 2, 2008
Bridgit software	3.3.23.0	January 10, 2008
SMART Product Update	1.1.9.0	

Computer requirements

Windows operating systems

- Pentium II 450 MHz processor
- 256 MB of RAM (512 MB recommended)
- 180 MB of free hard disk space for minimum installation (840 MB for full installation with Gallery collections)
- Windows 2000, Windows XP or Windows Vista operating system
- Internet Explorer Internet browser 6.0 or later
- Adobe Flash Player 8

Mac OS X operating system software

- 700 MHz processor (1 GHz or faster recommended) PowerPC G3, G4 or G5 processors or Intel processors (universal binary)
- 256 MB of RAM (512 MB recommended)
- 85 MB of free hard disk space for minimum installation (825 MB for full installation with Gallery collections)
- Mac OS X operating system software 10.4.11 or 10.5.4
- Safari application program 1.3.2 or later

Known issues

Windows operating systems

- When you use a SMART Board V200 series interactive whiteboard, you must project the image to cover the entire surface. Otherwise, orientation doesn't work properly.
- The SMART Board V200 series interactive whiteboard doesn't support USB 1.0. In some situations, connecting a SMART Board V200 series interactive whiteboard to a computer through USB 1.0 causes the computer to reboot repeatedly.
- In rare situations, customizing Floating Tools can cause the tools to stop responding.
- Double-clicking in PowerPoint presentation graphics program while in presentation mode doesn't work properly.

Mac OS X operating system software

- If your Mac computer enters sleep mode, it loses the connection to the SMART Board 600 series whiteboard after it exits sleep mode. Restarting the computer restores the connection.
- In rare situations, customizing Floating Tools can cause the tools to stop responding.
- If you connect your Mac computer with SMART Board drivers to a Unifi™ 35 projector and then restart the computer, SMART Board Tools is no longer able to detect the SMART Board interactive whiteboard.

Contact us

If you experience difficulty with your SMART product, please contact your local reseller before contacting SMART Technical Support. Your local reseller can resolve most issues without delay.

NOTE

To locate your local reseller, visit smarttech.com/where.

All SMART products include online, telephone, fax and e-mail support:

Online	smarttech.com/contactsupport
Telephone	+1.403.228.5940 or Toll Free 1.866.518.6791 (U.S./Canada) (Monday to Friday, 5 a.m. – 6 p.m. Mountain Time)
Fax	+1.403.806.1256
E-mail	support@smarttech.com

Feedback

Did this document provide the information you were looking for? If you have any questions or suggestions about how we can improve this or other SMART documents, please e-mail us at DocumentationFeedback@smarttech.com.